CENTERS FOR MEDICAR BTATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/BUPPLIER/CLIA IDENTIFICATION NUMBER:		TIPLE CONSTRUCTION	OMB NO. 0938-038	
		ļ ·	A. BUILDII	NG 01 ,,	COMPLETED	
		185141	B. WING_		C 01/06/2011	
NAME OF PROVIDER OR SUPPLIER				REET ADDRESS, CITY, STATE, ZIP C		
	JRE HEALTHCARE O			102 POCAHONTAS TRAIL GEORGETOWN, KY 40324		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES Y MURT BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	N SHOULD BE COMPLÉTIO E APPROPRIATE DATE	
K 000	INITIAL COMMENT	5 8	K 000			
K 027	Investigating ARQ # 01/05/2011 and con KY00015788 was s cited.	Safety Code Survey, KY0015788 was initiated on Icluded on 01/06/2011. ARO # ubstantiated with a deficiency	K 027	JAN 2 7 20		
	Door openings in smoke barriers have at least a 20-minute fire protection rating or are at least 1%-inch thick solld bonded wood core. Non-rated protective plates that do not exceed 48 inches from the bottom of the door are permitted. Horizontal sliding doors comply with 7.2.1.14. Doors are self-closing or automatic closing in accordance with 19.2.2.2.6. Swinging doors are not required to swing with egress and positive latching is not required. 19.3.7.5, 19.3.7.6, 19.3.7.7			K 027 Immediate Corrective Acti Found To Be Affected No specific resident(s) identif Maintenance Director in no negative effect on an within the immediate are survey was conducted. S to replace doors indicated	dicated there was y resident located as at the time the	
	Based on observation determined the facility described doors located resist the passage of close all the way to I reaching other parts situation. The deficit	not met as evidenced by: on and interview, it was ity failed to ensure cross ed in a smoke barrier would if smoke. These doors must nelp prevent fire/smoke from of the building in a fire ency has the potential to compartments, sixteen (16) visitors.		performed by Regional Pl Manager on 01/07/2011 Identification of Other Reside Potential to be Affected An audit of all corridor of performed by Maintenance 01/06/2011 to assure proper doors sealed as required resident(s) were identified.	Plant Operations sidents With The or fire doors was unce Director on toper closer. All and thus no other	
	The findings include: Observation on 01/05/2011 at 4:54 PM, with the Regional Plant Operations Manager, revealed the smoke doors located on the 100 Hall had a gap at the top of the doors.			Measures Taken To Assure Be a Recurrence Selected contractor will identified as soon as prace	replace doors	
	<u> </u>	RISUPPLIER REPRESENTATIVE'S SIGNA	TURE	of doors, but no later than	02/20/2011 (xs) DATE	
	THE	2/2		on may be excused from correcting	01/07/2011	

DEPAR	TMENT OF HEALTH	AND HUMAN SERVICES				PRINTED): 01/2 ⁰ /2011	
CENTE	RS FOR MEDICARE	& MEDICAID SERVICES			•	FORN OMB NO	1 APPROVED 1. 0938-0391	
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/OLIA IDENTIFICATION NUMBER: 185141			· 1	AULTIPI ILDING	E CONSTRUCTION 01	(X3) DATE S	(X3) DATE BURVEY COMPLETED	
			B. WING				С	
NAME OF P	ROVIDER OR SUPPLIER			OTOG	ET ADDRESS CITY OF THE	01/0	01/06/2011	
SIGNATU	JRE HEALTHCARE OI	FGEORGETOWN		102	et address, city, state, zip Pocahontas trail Orgetown, ky 40324	CODE	•	
(X4) ID PREFIX TAG	BUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		. ID PREP TAG	ıx	PROVIDER'S PLAN OF (EACH CORRECTIVE ACT CHOSS-REPERENCED TO TO DEFICIENCE	ION SHOULD BE HEAPPROPRIATE	(X6) COMPLETION DATE	
	Continued From page 1 Interview on 01/05/2011 at 4:64 PM, with the Regional Plant Operations Manager, revealed the facility would order a new set of smoke doors, to ensure the requirements of the Life Safety Code were met. Reference: NFPA 101 (2000 edition) 8.3.4.1* Doors in smoke barriers shall close the opening leaving only the minimum clearance necessary for proper operation and shall be without undercuts, louvers, or grilles.		K	Corridor fire doors will be Maintenance Quality Ass Report beginning Janua assure proper closer and se Monitoring Changes To Ass Compliance Maintenance Director/des report shall be submitted Assurance Committee at le review and revision un Assurance committee has compliance is achieved. Peters Committee to Maintenance is achieved.			nurance Inspection ry 31, 2011 to eal. sure Continuing signee inspection to the Quality east Quarterly for hil the Quality determined 100%	
					Date of Completion:		02/20/2011	
			•	,		•		